

## CROSS REFERENCE GUIDE

---

### Signal Relay

| HONGFA | OMRON | PANASONIC | TE     |              |          |             | NEC     |
|--------|-------|-----------|--------|--------------|----------|-------------|---------|
|        |       |           | TYCO   | AXICOM       | OEG      | P&B         |         |
| HFD23  | G5V-1 | HY        | V23111 |              | TSC      |             | TY      |
| HFD27  | G5V-2 | DS2Y      |        | D2N (V23105) | OVR/ORZ  | T82/T85/190 | MR62    |
| HFD2   | G6A   | DS2Y      | V23042 | MT2          |          |             | MR82    |
| HFD3   | G6S   | TX        |        | P2 (V23079)  |          |             | EC2/ED2 |
| HFD31  | G6H   | TQ        |        | FP2          |          |             | EA2     |
| HFD4   | G6K   | AGQ       |        | IM           |          |             |         |
| HFD41  | G2E   |           |        | V23101       | OUA/OUAZ | T81         |         |
| HFD41A | G2E   |           |        | V23101       | OUA/OUAZ | T81         |         |

(To be continued)

| HONGFA | FUJITSU           | FEME    | FINDER | SONGCHUAN |
|--------|-------------------|---------|--------|-----------|
| HFD23  | SY                | EZ-EZH  |        |           |
| HFD27  | FBR244/ FTR-C2/RY | ZFH-002 | 30.22  | 876       |
| HFD2   | RA                | TF/TFL2 |        | 502       |
| HFD3   | BA/NA             |         |        | 902       |
| HFD31  | A                 |         |        |           |
| HFD4   |                   |         |        |           |
| HFD41  | FBR211SC/MZ       |         |        | 842       |
| HFD41A | FBR211SE/MZ       | ESH-001 |        | 842A      |

This table is just for reference.if you have any questions,please contact our local agent or send e-mail to marketing@hongfa.com.



HONGFA RELAY

ISO9001, ISO/TS16949 , ISO14001, OHSAS18001, IECQ QC 080000 CERTIFIED

2012 Rev. 1.00